Declassified IAW E.O. 12958 by the Air Force Declassification Office and Approved for Public Release.

Date: 817-bb



K717.9413-207 24 Sep 1973 c.1 0414-41

# 

# "INK" DEVELOPMENT AND EMPLOYMENT

20080910246


K717.414-41 c. 2

(IHI2 COAFK I2 ONCTW22TLIFD)

Declassified IAW E.O. 12958 by the Air Force Declassification Office and Approved for Public Release.

Date: 8.17-06





# "INK" DEVELOPMENT AND EMPLOYMENT

24 SEP 73

HQ PACAF
Directorate of Operations Analysis
CHECO/CORONA HARVEST DIVISION

Prepared by:

Major B.H. Barnette Jr.
Project CHECO 7th AF



### REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

of information, incl (0704-0188), 1215 subject to any penal	uding suggestions for Jefferson Davis High ty for failing to comp	or reducing the bur way, Suite 1204, And ity with a collection of IR FORM TO TI	rden, to Department of Defens rlington, VA 22202-4302. Res of information if it does not displa HE ABOVE ADDRESS.	se, Washington He pondents should be ay a currently valid	adquarters s aware that OMB control	notwithstanding any other provision of law, no person shall be number.							
	TE (DD-MM-YY		ORT TYPE			3. DATES COVERED (From - To)							
4. TITLE AND	SUBTITLE				5a. COI	NTRACT NUMBER							
				5b. GRANT NUMBER									
				5c. PROGRAM ELEMENT NUMBER									
6. AUTHOR(S)					5d. PROJECT NUMBER								
					5e. TAS	SK NUMBER							
					5f. WO	RK UNIT NUMBER							
Department of	the Air Force Pacific Air Force	ON NAME(S) AI		8. PERFORMING ORGANIZATION REPORT NUMBER									
9. SPONSORIN	IG/MONITORING	3 AGENCY NAM	ME(S) AND ADDRESS(ES)	)		10. SPONSOR/MONITOR'S ACRONYM(S)							
						11. SPONSOR/MONITOR'S REPORT NUMBER(S)							
12. DISTRIBUT	ION/AVAILABIL	ITY STATEMEN	Т										
A Approved	for Public Rel	ease											
13. SUPPLEME	NTARY NOTES												
14. ABSTRACT													
Project CHECO was established in 1962 to document and analyze air operations in Southeast Asia. Over the years the meaning of the acronym changed several times to reflect the escalation of operations: Current Historical Evaluation of Counterinsurgency Operations, Contemporary Historical Evaluation of Combat Operations and Contemporary Historical Examination of Current Operations. Project CHECO and other U. S. Air Force Historical study programs provided the Air Force with timely and lasting corporate insights into operational, conceptual and doctrinal lessons from the war in SEA.													
15. SUBJECT T		ar, War in Sou	theast Asia, Vietnam V	War- Aerial Op	perations	, American							
16. SECURITY	CLASSIFICATIO	N OF:	17. LIMITATION OF		19a. NA	ME OF RESPONSIBLE PERSON							
a. REPORT	b. ABSTRACT	c. THIS PAGE	ABSTRACT	OF PAGES	19b. TEL	EPHONE NUMBER (Include area code)							

DEPARTMENT OF THE AIR FORCE

HEADQUARTERS PACIFIC AIR FORCES
APO SAN FRANCISCO 96553



### PROJECT CHECO REPORTS

The counterinsurgency and unconventional warfare environment of Southeast Asia has resulted in USAF airpower being employed to meet a multitude of requirements. These varied applications have involved the full spectrum of USAF aerospace vehicles, support equipment, and manpower. As a result, operational data and experiences have accumulated which should be collected, documented, and analyzed for current and future impact upon USAF policies, concepts, and doctrine.

Fortunately, the value of collecting and documenting our SEA experiences was recognized at an early date. In 1962, Hq USAF directed CINCPACAF to establish an activity which would provide timely and analytical studies of USAF combat operations in SEA and would be primarily responsive to Air Staff requirements and direction.

Project CHECO, an acronym for Contemporary Historical Examination of Current Operations, was established to meet the Air Staff directive. Based on the policy guidance of the Office of Air Force History and managed by Hq PACAF, with elements in Southeast Asia, Project CHECO provides a scholarly "on-going" historical examination, documentation, and reporting on USAF policies, concepts, and doctrine in PACOM. This CHECO report is part of the overall documentation and examination which is being accomplished. It is an authentic source for an assessment of the effectiveness of USAF airpower in PACOM when used in proper context. The reader must view the study in relation to the events and circumstances at the time of its preparation—recognizing that it was prepared on a contemporary basis which restricted perspective and that the author's research was limited to records available within his local headquarters area.

ROBERT E. HILLER

Kohert & 14

Director of Operations Analysis

DCS/Operations

### DEPARTMENT OF THE AIR FORCE

HEADQUARTERS PACIFIC AIR FORCES APO SAN FRANCISCO 96553

REPLY TO ATTNOT DOAD

24 September 1973

Project CHECO Report, "'INK' Development and Employment"

### 10 SEE DISTRIBUTION PAGE

- 1. Attached is a SECRET document. It shall be transported, stored, safeguarded, and accounted for in accordance with applicable security directives. Retain or destroy in accordance with AFR 205-1. Do not return.
- 2. This letter does not contain classified information and may be declassified if attachment is removed from it.

FOR THE COMMANDER IN CHIEF

V. H. GALLACHER, Lt Colonel, USAF V. H. GALLACHER, Lt Colonel, USAF
Chief, CHECO/CORONA HARVEST Division
Directorate of Operations Analysis

1 Attachment
Project CHECO Report (S),
24 September 1973 DCS/Operations

1 Attachment

### DISTRIBUTION LIST

1.	SEC	CRETARY OF	THE	AIF	RF	OF	RCE		i.	AFSI							1
	b. c.	SAFAA SAFLL SAFOI SAFUS	• •					1 2 1		(2)	AFLGX AFLGF AFLGT AFLGY				•	•	1 1 1
2.		ADQUARTERS (	JSAF						j.	, ,	AFXOD	•		•	•	•	1
	a.	AFNB		٠		•	•	1		(2) (3) (4)	AFXODO AFXODO AFXODO			•	•	•	1
	b.	AFCCS (1) AFCCN (2) AFCVC (3) AFCHOS	: :					1 1 2		(5) (6) (7) (8)	AFX000 AFX00S AFX00S	SN 50				•	11111
)		AFCSA (1) AF/SAG (2) AF/SAM		:				1		(10) (11)	AFX00S AFX00S AFX00S	SV SR SW				•	1 1 1
	d.	AFIGO (1) AFOSI/: (2) IGS .	IVOA					3		(14) (15)	AFXOXA AFXOXA	(G					6
	e.	AFIS/INTC			•	•		5			COMMANE	)					
	f.	AFODC (1) AFPRC (2) AFPRE (3) AFPRM						1	a.	(1)	HEADQU (a) XF (b) DC	PSY	ERS	•			1
	g.	AFPDC (1) AFDPW						1		(2)	(c) II			,	•		1
	h.	AFRD (1) AFRDP (2) AFRDQ (3) AFRDQPO (4) AFRDR	· ·					1 1 1 1		(2)	(a) 12 (a) 12 (b) 13 (c) US	DAF (	00 .				1 1 1

- 10 m	(3)	WINGS (a) 1SOW(DOI) 1 (b) 23TFW(DOI) 1 (c) 27TRW(DOI) 1 (d) 33TFW(DOI) 1 (e) 35TFW(DOI) 1	d.	ADC (1) HEADQUARTERS (a) DOA
		(f) 366TFW(DOI) . 1 (g) 67TRW(DOI) . 1 (h) 316TAW(DOX) . 1 (i) 317TAW(DOI) . 1		(2) AIR DIVISIONS (a) 25AD(DOI) 1 (b) 20AD(DOI) 1
		(j) 474TFW(DOI) . 1 (k) 463TAW(DOX) . 1 (l) 58TAC FTR TNG		ATC (1) DOSPI 1
		WG 1 (m) 354TFW(DOI) . 1 (n) 314TAW(DOI) . 1	f.	AFSC (1) HEADQUARTERS (a) XRP 1 (b) SDA 1
	(4)	TAC CENTERS, SCHOOLS  (a) USAFTAWC(IN) . 1  (b) USAFTFWC(DR) . 1  (c) USAFAGOS(EDA) 1		(c) HO
b.	SAC (1)	HEADQUARTERS (a) XPX 1 (b) LG 1 (c) IN 1	q.	(h) ESD(YWA) 1 (i) AFATL(DL) 1 (j) ESD(XRP) 1
		(d) NR 1 (e) HO 1	3.	(1) HEADQUARTERS (a) AFSCC(SUR) 2
	(2)	AIR FORCES (a) 2AF(IN) 1 (b) 8AF(DOA) 2 (c) 15AF(INCE) 1		USAFSOS (1) HEADQUARTERS (a) ESD 1
с.	MAC (1)	HEADQUARTERS   (a) DOI	i.	PACAF (1) HEADQUARTERS (a) DP
	(2)	MAC SERVICES (a) ARRS(XP) 1		(g) DOAD 6

	(2)		FORCE:						4.		PARATE OPER
			1. CS 2. XP 3. DO		•	•	1				DMAAC/PR .  AFRES(XP)
		(b)		CSH)	HE	(0)	1 2				3825 Acad
	(3)	(a)	DIVIS 313AD	(DOI)			1				(1) ACSC-E (2) AUL/LS (3) HOA
		(c)	314AD 327AD	(IN)	•	•	1			d.	ANALYTIC S
	(4)	WING		ווסאו			1			e.	AFAG(THAIL
			8TFW(			•	1				
		(c)	388TF 405TF	W(DO)			1				
		(d)	405TF	M(DOI	)	•	1				٠
		(e)	432TR	M(DOI	)	•	1				
		(T).	1st T (DA)			•	1				
j.	USAF		DQUART	ERS							
	(.,		DOA			•	1				
		(b)	DOLO			•	1				
			DOOM		•	•	1	,			
		(d)	XP .		•	•	1				
	(2)	(a)	FORCE 3AF (D	0) .		•	1				
		(b)	16AF(	DO) .	•	•	1				
	(3)	WIN									
		(a)	50TFW	(DOA)		•	1				
		(p)	20TFW	(DOI)		•	7				
		(c)	401TF	MIDCL	11)	•	1				

SEF	PARA	TE	OPE	RA	TI	NG	A	GE	NC	IES	5
a.	DMA	AC/	PR		•	•		•		•	1
b.	AFR	ES(	XP)	)	•	•	•	•	•	•	2
c.	3829 (1) (2) (3)							. 8	•	•	1 2 2
d.	ANA	LYT	IC	SV	s,	I	NC		•	•	1
e.	AFA	G(T	'HA]	[LA	ND	)	•	•	•	•	1
	•										

5.	MIL	ITARY DEPARTMENTS, UNIFIED AND SPECIFIED COMMANDS, AND JOINT STAFFS
	a.	COMUSJAPAN/J3
	b.	CINCPAC (J301)
	c.	CINCPAC (J301)
	d.	CCMUSKORFA (ATTN: J-3)
	e.	COMUSMACTHA I/MACTJ3
	f.	COMUSTDC (.13)
	g.	COMUSTDC (J3)
	h.	CINCLANT (CL)
	i.	그렇게 깨끗하면서 그렇게 하면 하는 이 이렇게 하는 이 이렇게 하는 것이 되었다. 그는 그에 그가는 그리고 있는 그래요 하는 그래요
		COMMANDANT MADINE CORDS (APO)
	j.	COMMARIDANT, MARINE CORPS (ABQ)
	k.	CINCONAD (COOP) DEPARTMENT OF THE ARMY (ASM-D)
	1.	DEPARTMENT OF THE ARMY (ASM-D)
	m.	JOINT CHIEFS OF STAFF (J3RR&A)
	n.	JSTPS
	0.	SECRETARY OF DEFENSE (OASD/SA)
	p.	CINCSTRIKE (STS)
	q.	CINCAL (J2)
	r.	CINCSTRIKE (STS)
	S.	U.S. DOCUMENTS OFFICE, HQ ALLIED FORCES NORTHERN EUROPE 1
6.	SCH	OOLS .
	a.	Senior USAF Representative, National War College
	b.	Senior USAF Representative, Armed Forces Staff College 1
	c.	Senior USAF Rep, Industrial College of the Armed Forces 1
	d.	Senior USAF Representative, Naval Amphibious School 1
	e.	Senior USAF Rep, U.S. Marine Corps Education Center 1
	f.	Senior USAF Representative, U.S. Naval War College 1
	g.	Senior USAF Representative, U.S. Army War College 1
	h.	Senior USAF Rep, U.S. Army C&G Staff College
	i.	Senior USAF Representative, U.S. Army Infantry School 1
	j.	Sonior USAF Pan USA JEK Can for Mil Asst
	k.	Senior USAF Rep, USA JFK Cen for Mil Asst
	î.	Senior USAF Representative, U.S. Liaison Office
		Senior USAF Rep, U.S. Army Armor School, Comd and Staff Dept. 1
	m.	Sentor bon kep, b.s. Army Armor Sendor, come and Starr bept. I
7.	SPE	CIAL
	a.	The RAND Corporation

### TABLE OF CONTENTS

																												Page
LIST OF	ILL	USTR	ATI	ONS	SA	ANE	) 7	TAI	BLI	ES	•	•	•		•	•	•	•	•	•	•	•	•	•	•	•	•	ix
EDITOR'	S NO	TE			•	•				•			•	•		•	•	•	•	•	•	•	•	•	•		•	Х
CHAPTER																												
I.	INT	RODU	CTI	ON				•					•	•	•			•	•	•	•			•	•	•	•	1
II.	DEV	ELOP	MEN	IT			•		•	•	•	•	•		•		•	•	•		•	•	•		•	•	•	6
		HAV																										
		HAV	BAT	II	NK.		•	•	•	•	•	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	6
III.	COM	BAT	EVA	LUA	AT I	101	١	(C(	OR	DIVIE	ET	II	NK)	)	•	•	•	•	•		•	•	•	•	•	•	•	16
IV.	SUM	MARY	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	35
APPENDI	х.					•	•	•	•	•	•	•	•	•	•	•	•			•	•	•	•			•	•	37
F00TN0T	ES					•		•	•	•		•	•	•	•		•	•	•	•	•	•		•	•	•	•	39
CLOCCAD	V																											45

viii

# UNCLASSIFIED Xi 10 LIST OF ILLUSTRATIONS Figure No. Page xi 2. Reflectance Data for Filter Selection . . . . . . 3 14 15 5. STEEL TIGER (Areas 1-9) ....... 20 LIST OF TABLES Table No. Page

ge

### EDITOR'S NOTE

The author, Major Benjamin H. Barnette, Jr., is a senior navigator and a Distinguished Graduate of the Air Command and Staff College (ACSC). While attending ACSC, he earned a Master of Science degree in Counseling and Guidance from Troy State University. Prior to attending ACSC, Major Barnette spent several years as a navigator in the Military Airlift Command (MAC) and served in various capacities in the personnel field, including a tour on the DCS/Personnel staff at Hq MAC.

The publication copy of this report was prepared and edited by Miss Carolyn E. Carlson, Hq PACAF/DOAD.



INK In Action

FIGURE 1

### CHAPTER I

### INTRODUCTION

On 15 August 1971, a Forward Air Controller (FAC) using INK equipment on a mission over the STEEL TIGER area of Laos received eight to 10 indications of interdiction targets. He passed this target on to two other FACs, one of whom "reported seeing nothing but trees but requested ordnance on the strength of [the] INK returns. . . . The total Bomb Damage Assessment (BDA) from subsequent airstrikes against this INK target was:

19 medium secondary explosions, 66 small secondary explosions, one large and five medium sustained fires."

But what was the INK equipment which permitted the operator to see through jungle canopy and spot camouflaged men and equipment where the unaided eye could see "nothing but trees"? How did it begin, what was the course of its development, and what overall conclusions can be drawn with reference to its employment in Southeast Asia (SEA)? The task of this report is to answer these questions.

As the enemy continued to move his war material south toward the Republic of Vietnam (RVN) along the intricate maze of jungle roads and trails known as the Ho Chi Minh Trail, the United States Air Force (USAF) constantly sought new methods of detecting and countering his presence. Although FACs continually scanned the infiltration routes, visual reconnaissance (VR) was severely limited by the double and triple canopy jungle, and small North Vietnamese Army (NVA) and Viet Cong (VC) units were especially difficult to find.


Then in April 1966 the Air Force accepted on contract an unsolicited proposal by Plessett Corporation based on Dr. John Monroe's concept of 3 cloth (man-made camouflage) detection through rotating filters. It promised significant improvements in both VR capability over heavily canopied jungle and in the detection of small enemy contingents. The Air Force designated the initial program HAVE INK, and the first prototype was ready for testing in January 1967. Development of an electro-optical, daytime reconnaissance device giving a real-time camouflage detection capability was well underway.

The technical basis for the detection concept (see Figure 2) was that in the near-infrared (IR) and visual part of the frequency spectrum from approximately 0.72 to 1.2 microns the reflectance of virtually all natural materials increases moderately and quite uniformly as wavelength increases. While there would be bright and dull shades, a scene viewed at those wavelengths would have a monochromatic appearance.

Although blending into natural backgrounds to the naked eye, many manmade materials and particularly many camouflaged fabrics had distinctively different reflectances in that frequency spectrum.

When camouflaging mobile objects where complete masking by natural vegetation was not possible, the North Vietnamese employed two fundamental techniques: (1) "the object was made to have an irregular outline, usually by the use of relatively small portions of natural vegetation, while allowing complete freedom of movement," and (2) the object was made to match the contrast of its background. "This meant coloring the object to approximate the visible color of the dominant component of the background." Often,

# CONFIDENTIAL



WET LOAMY SOIL —————
TROPICAL GREEN LEAVES ————
BARK AND TWIGS —————
DRAB UNIFORM CLOTH ————

Reflectance Data For Filter Selection

FIGURE 2

CONFIDENTIAL

the North Vietnamese used irregular paint patterns to break up the outline and to reduce contrast against a conglomerate background. With the development of camouflage detection (CD) film, "the meaning of contrast matching was extended to include matching both in the visible and near-IR spectral regions." Matching dyes and paints against a chlorophyll background was relatively successful across both regions.

The inventor of the HAVE INK . . . concept recognized that although camouflage designers could match chlorophyll in the CD film band, no dyes existed that possessed the very rapid increase in reflectance of chlorophyll in the region from 0.70 to 0.75 micron. . . . He correctly asserted that, due to this particular shortcoming of the man-made camouflage dyes, they would be discernible from the natural background when observed alternately through two narrow bandpass filters, one centered at 0.74 micron and the other at about 1.0 micron.

This then became the basis for the design of a monocular (initially) and binocular (subsequently) detector using two rotating filters passing alternately across the field of view. The general tropical background (green leaves, bark, and soil) had a known curve of reflectance versus light wavelength, while the man-made dyes used in uniforms and camouflage cloth had a different curve. By using two wavelengths some distance apart in the spectrum and passing filters screening out all but these two wavelengths alternately across the field of view, the background appeared at a constant intensity, while man-made cloth objects appeared to pulsate. Some of the camouflage paint on vehicles, guns, and other material gave the same effect.

Advantages of this type of detector were threefold: First, form recognition was not required. The FAC no longer had to "mentally pick the form

or shape of the camouflaged object from the surrounding shadows or covering branches." Regardless of how well the lines, edges, color, and form of the object had been made to blend with the surroundings, "any part of the material viewed through the detector" would pulsate. Second, since the detector was "optimized for reflected near-IR light" and since substantially larger quantities of light in these wavelengths were available on the ground under a moderately forested canopy, one could see much more through the INK detector than with the naked eye or binoculars if the canopy were open enough to permit vision to the ground. Third, since "contrast alone" was sufficient for target identification, the surveillance area of the detector was considerably larger than was possible for systems which

This then was the theoretical basis for the INK program. The Air Force sought to translate the theory into equipment suitable for operational employment in SEA during 1971 and 1972.

### CHAPTER II

### DEVELOPMENT

### HAVE INK

As noted in the previous chapter, Air Force development of camouflage detection equipment began in April 1966 under the project title, HAVE INK, and the Air Force Weapons Laboratory (AFWL) completed the first prototype 13 in January 1967. Rome Air Development Center (RADC) personnel in conjunction with the AFWL tested the unit at Eglin AFB, Florida, in October and November 1967 and found that it yielded "twice the detection capability of visual reconnaissance using targets simulating stationary, camouflaged troops. . . . It is important to note that this increased effectiveness was attained by virtually untrained operators using relatively primitive 14 equipment." The test "conclusively demonstrated the existence of a 15 unique target signature for many military uniforms and material."

### HAVE INK II

As a result of the test, the AFWL began modifications to extend the range of the prototype under the informal designation of HAVE INK II. They "increased the magnification to 8-1/2 power, incorporated an image stabilizer, and took this improved detector to Southeast Asia for a demonstration of 16 its capability." The demonstration under combat conditions, begun in December 1967 and concluded in January 1968, "proved the potential usefulness of the system." Although limitations of the equipment required considerable modification prior to any extended operational employment, in January 1968 the 7th Air Force Commander, General Momyer, requested five improved systems

for use by 7th Air Force personnel in SEA. In July 1968, Hq USAF authorized the required additional development and procurement by the Aeronautical 18
Systems Division (ASD) of Air Force Systems Command (AFSC).

### COMBAT INK

The immediate task of this new development, nicknamed COMBAT INK, 19 was to correct the deficiencies discovered during the SEA demonstration.

Specifically, "the detection range was to be increased to 4,500 feet. The diameter of the surveillance area was to be increased to 300 feet. The filter balance was to be externally controllable . . . [and] a number of image-tube deficiencies were to be corrected." Basically, these were requirements for increased range and resolution, background balance control, ("trim"), and built-in image stabilization. Further requirements were an effective way to correlate observed returns with visual references, binocular instead of monocular viewing, and a weight reduction of the detector head from the 10.5 pounds of the SEA demonstrator.

By virtue of its role in the initial HAVE INK prototype development, the AFWL undertook the COMBAT INK effort. It received funding approval on 27 July 1968, and contractor effort began on 28 August 1968. AFWL procured a sixth device for the Marine Corps and, at one point, it ordered a seventh set (later cancelled due to cost) so that further exploitation and production engineering could be conducted even during the operational 21 test and evaluation (OT&E).

Although originally scheduled for delivery during February 1969, the first set did not arrive until September 1969. After a short evaluation

USAF returned it to the contractor for "elimination of defects and reconfiguration of controls." The remaining five sets arrived at the USAF Special Operations Force (USAFSOF) at Eglin AFB, Florida, during 22 February 1970 to begin the OT&E phase.

The purpose of this OT&E was "to determine the operational capability of the INK detector to detect camouflaged objects." Specific 23 objectives were to determine the:

- a. Accuracy of target detection in relation to terrain and foliage.
- b. Most effective altitude for target detection.
- c. Concept of employment.
- d. Operational and engineering deficiencies.
- e. Maintenance and logistical requirements.
- f. Personnel resource and training requirement to provide maintenance support.
- g. Operator training program required.
- h. System reliability.

To insure realistic (tropical) environmental evaluation, USAFSOF conducted the majority of tests in the Panama Canal Zone jungle area near Howard Air Force Base (AFB). However, they accomplished airborne specification testing in the semi-tropical areas around Eglin AFB, Florida.

The INK equipment was flight tested in 0-1E, 0-2A, and U-10B aircraft (through an open door or window) and taxi tested through-the-canopy on the OV-10A. Since most 0-1Es were no longer in the U.S. combat inventory, USAFSOF eliminated them from further consideration. Tests were conducted

in the U-10B since it was readily available in the Canal Zone and required no modification for INK installation. However, since it was not a FAC aircraft, it was not considered further. Testing in the OV-10A was conducted only on the ground since the INK equipment impeded normal ejection seat operation. As costs for an installation which would have been safe in flight were prohibitive, the USAFSOF dropped the OV-10A as a likely prospect. Thus the O-2A emerged as the best aerial platform.

In the Canal Zone, aerial operators tested the INK equipment against the following targets: "North Vietnamese and Viet Cong uniform halves, U.S. fatigue halves and jackets, U.S. general purpose netting, U.S. jeep canvas top, North Vietnamese hammocks, U.S. jeeps and trucks, U.S. artillery pieces (105 millimeter howitzers), and U.S. Army troops in combat uniforms." All were detectable except the paint on U.S. military vehicles and approximately 50 percent of the canvas tops on U.S. vehicles. "In general, if the jungle canopy contained nine-inch holes or larger, targets could be picked out by the INK system. If the jungle canopy was more closed than that, complete concealment of the target resulted." Although some natural targets, such as gravel roads, water puddles, tin roofs, and asphalt and concrete areas, also pulsated, the trained operator had no difficulty in differentiating between the camouflaged and natural ones.

The equipment detected targets best at an altitude of 3,200 feet above ground level (AGL) and at an angle of 45 degrees to the ground, although it was tested at altitudes from 500 feet to 10,000 feet AGL. At altitudes below 3,000 feet AGL, the rapid angular rate of change to the target and greater

turbulence\* hindered detection. Operators could resort to altitudes above 27
3,200 feet if enemy antiaircraft artillery (AAA) forced them upward.

Flown under a wide range of light conditions, the system functioned well from one hour after sunrise until one hour before sunset regardless of cloud cover\*\* as long as line of sight to the target could be maintained. The aircrews conducting the test flew a circular, right-hand orbit around the target usually making more than one orbit and often spending 15 minutes on one area 500 feet in diameter.

All operational and engineering deficiencies discovered during the test were attributed to "engineering deficiencies or manufacturing defects" and consisted mainly of leaking stabilizer subsystems, defective image tubes, and stopping filter motors. Spare parts and technical support were not available for most of the OT&E since Plessett Corporation, which had become a division of EG&G, had ceased operations (and their technical knowledge was lost) upon delivery of the fifth INK system to USAFSOF during February 1970. Therefore, the Air Force had to establish its own maintenance capability 29 and supply support.

USAFSOF personnel developed operator and maintenance training courses, including writing the necessary manuals, and designed and built all required 30 test equipment. Based on their experience with the equipment, USAFSOF stated that a 25 percent failure rate for new operators could be expected

<sup>\*</sup>The INK equipment will operate in turbulence up to, but not including, moderate turbulence.

<sup>\*\*</sup>During the later combat evaluation in SEA (CORONET INK), operators found that three miles visibility or more than 3/8 cloud cover reduced the capability of the system and that 4/8 cloud cover resulted in marginal performance.

due to some individuals not being able to adapt to the "flicker threshold phenomena." The constant flickering could cause some persons to have an epileptic seizure, lose consciousness, or became confused.

Numerous manufacturing defects and engineering deficiencies in the five systems made it difficult to assess system reliability. "Although all five systems were delivered to USAFSOF as operational after being ground tested by AFWL, only one system remained operational after one week of airborne testing." That one system was tested, however, to see if the others merited costly repairs and redesign—the final determination was 32 that they did.

By mid-April 1970, most of the OT&E was complete. In July 1970, USAF approved the additional funding, and three contracts were awarded for the required work and spare parts procurement. For the next five months, none of the units were operational since all were in the repair and redesign phase and in some state of disassembly. However, all of the sets were operationally ready two weeks prior to the completion of the OT&E in January 1971.

In addition, a 90-day parts supply kit had been assembled based on usage rates during the OT&E. It was "not 100 percent spared and items 36 not considered field repairable . . . were omitted."

The final conclusions of the OT&E were:

a. The INK system is capable of detecting a 9-inch diameter of U.S. fatigue cloth or North Vietnamese green uniform cloth material from 4,500 feet slant range. The system can also detect a mansize, uniformed target of the same materials

from 14,000 feet slant range.\* This capability exists for line-of-sight conditions with tropical or semi-tropical backgrounds.

- b. The INK system should be used in jungle environments in 0-2A aircraft operating between 1 hour after sunrise to 1 hour before sunset. Search altitudes should be between 1,000 feet and 10,000 feet AGL, using the most effective altitude of 3,200 feet AGL if weather and enemy defenses permit. The search pattern should be a right-hand orbit about the area to be searched.
- c. Within the selected concept of employment, the system has no operational deficiencies. The engineering deficiencies that were identified during the test were corrected prior to test completion.
- d. Air Force maintenance of the INK system is feasible.
- e. The maintenance technician training course requires 40 classroom hours, and AFSC 301XX is a usable resource for personnel.
- f. The operator training program requires 3 classroom hours and approximately 10 flying hours.
- g. The reliability of the present system is unknown.

The equipment had progressed in design and development since Plessett Corporation built the initial HAVE INK prototype some four years earlier. In its final configuration and ready for SEA deployment, the system consisted of a detector head, control box, power supply, a battery source for ground use, and three interconnecting cables. (See Figure 3.) Only one battery was provided for the five systems; however, it could be recharged by plugging it into any 110 volt alternating current outlet. Installed in


<sup>\*</sup>Operating altitude of 10,000 feet AGL.

agnal

the aircraft, the equipment weighed 40 pounds, 24 pounds of which was the detector head. The detector head had increased from 10.5 to 24 pounds due to necessary engineering modifications.

The system gave the operator a "choice of 7- or 15-power viewing through the image intensifier tube and rotating filter" and provided an "image stabilized view of flickering targets." (See Figure 4.) If desired, he could replace the view through the image tube with a "direct unstabilized 3-power view by activating a solenoid-driven mirror." The three-power view allowed the operator to locate the targets seen through the image tube in relation to the surrounding terrain for target marking purposes.


At the conclusion of the COMBAT INK OT&E, USAFSOF recommended that the systems be deployed for combat evaluation.




INK System Components

FIGURE 3

# CONFIDENTIAL





INK Detector Head

(Schematic)

FIGURE 4

CONFIDENTIAL

CHAPTER III

### COMBAT EVALUATION

(CORONET INK)

The Chief of Staff, U.S. Air Force, implemented TAC OPLAN 19 governing the redeployment and SEA evaluation of the INK system (nicknamed CORONET 41 One week later, on 2 February 1971, the introduction team consisting of Major Richard E. Pierson and 1/Lt James N. Hutchinson departed Eglin AFB, Florida, enroute to the 20th Tactical Air Support Squadron (TASS), Da Nang Air Base (AB), RVN. Lt Hutchinson accompanied the five INK systems, 0-2A aircraft modification kits, spare parts, test equipment, manuals, and training materials directly to Da Nang AB arriving there 7 February 1971, while Major Pierson stopped enroute to 43 brief Hq PACAF and 7th AF personnel.

The purpose of the test was to

- • evaluate the INK system as a camouflage detector when used on 0-2A FAC aircraft during daytime, visual reconnaissance missions. Specific objectives of the test were to:
- a. Modify four 0-2A aircraft with INK system compatibility kits.
- b. Train three INK system maintenance personnel at operational site.
- c. Train six pilots as INK system operators at operational site.
- d. Refine combat tactics for INK system operational use.
- Evaluate combat results obtained by use of INK systems.

By 13 February 1971, all of the four required 0-2A aircraft had been modified to accept the INK equipment, 10 operators and two maintenance technicians were ready to begin training, and the evaluation was underway. The following day the FACs flew the first sorties.

The necessary 0-2A aircraft modification was relatively minor and the 20th TASS maintenance personnel performed it without difficulty. It 46 consisted of:

- a. Connecting the power supply through a 7 or 10 amp circuit breaker to the aircraft 28 volt direct current (DC) with a cannon plug.
- b. Replacing the aircraft door with a modified door which had a removable window and a suspension eyebolt on the upper window frame for the INK detector.
- c. Modifying the right seat rail with a locking pin hole in the extreme aft position.
- d. Removing the right rear seat from the aircraft.

As previously recommended by 7th Air Force, the 20th TASS was responsible for the INK equipment, which was under the operational control of the Military Region (MR) I Direct Air Support Center (DASC) for evaluation. The 0-2As equipped for the INK program flew within RVN and eventually in Laos and Cambodia. This provided an excellent opportunity for testing the INK equipment against a wide variety of terrain, foliage, targets, and enemy defenses. The selection proved to be a good one as the INK gear remained 47 with the 20th TASS during its entire stay in SEA.

Tactical Air Command (TAC) and 7AF envisioned a 60-day test period with the equipment to remain in operational use by 7AF personnel if combat

results warranted. Initially, the evaluation was to be restricted to missions within South Vietnam with later expansion into adjacent border areas if the devices proved successful and after appropriate combat tactics 49 had been developed.

Thus the INK systems were initially assigned in SEA to the "Speedy"

Tactical Air Control Party (TACP) or I TACP and operated along the road networks within MR I. Specifically they were used over "those parts of the Ho Chi Minh Trail terminating within and near the A Shau Valley and points North and South of there within 10 nautical miles of the Laotian/Republic of Vietnam border." (See Figure 5.)


Of the 10 operators initially selected for training, seven were FAC-qualified pilots and three were non-rated intelligence personnel. As it turned out, the three non-rated individuals were never placed on flying status, and two of the pilots were reassigned prior to the start of the training. However, the remaining pilots (plus two who were added later) were given three hours of ground training emphasizing familiarization with the equipment and best procedures for detecting targets. Following this, they began using the equipment in the air under the guidance of the introduction team. Project Officers considered the training complete when the operator began finding targets on a consistent basis.

The two electronics maintenance technicians (AFSC 301XX) received 40 hours each of classroom instruction and training using one of the INK systems as a working model. A third man, an electronics maintenance specialist, learned through on-the-job training (OJT).

Detection results were almost immediate. The first weekly "CORONET INK Status Report" submitted by I DASC covering the period 14 through 20 February 1971 contained the following statement: "Targets sighted this week: Eleven ten by twenty foot rectangular targets, one six by six foot square target, one three by eight foot rectangular target (he visually spotted supplies in the open after picking up the target), four small rectangular targets, three man targets moving on enemy road. All targets except three by eight supplies and men were invisible in direct three power viewing."

This proved to be the tenor of all subsequent weekly reports—numerous targets detected, most of which were invisible without the aid of INK.

As INK operators began using the equipment under actual combat conditions, they found that certain modifications of the tactics developed during the COMBAT INK OT&E were necessary. Whereas, in the Canal Zone, test personnel normally made more than one orbit and often spent 15 minutes on one area 500 feet in diameter, ground fire often made this impossible in SEA. Although the operators in Southeast Asia endeavored to do a complete 360 degree orbit about the target in order to get the best possible view of it, many times they had to do it in segments. One of the operators noted: "The minute that you flew a 15 to 20 degree arc in a 10 to 15 degree bank around the target and there was a gun down there, he would shoot at you. You were a sitting duck." Thus, they would fly approximately 10 seconds in an arc, break away, move back in on another section of the arc for 10 to 15 seconds, break away again possibly in the opposite direction, 54 and so on until they had viewed the target from all sides.



At the time the INK equipment was introduced into SEA, Operation LAM SON 719 was well underway. This was a "South Vietnamese three-divisionsized thrust into Laos along Route 9 between Khe Sanh and Tchepone conducted between 30 January and 24 March and supported by U.S. ground and After a brief familiarization period and in response to a I DASC request, 7AF on 3 March 1971 authorized I DASC to begin INK At this point, the 20th TASS FACs pressed their operations in Laos. INK support of the LAM SON 719 effort into Laos and continued through termination of the operation. Results are shown in Table 1. 22.) During this period, the Air Force employed the INK detection equipment over road networks in Laos (especially along Route 9), along the Ho Chi Minh Trail, and as part of Operation LAM SON 719 but only within 20 nautical miles of the Demilitarized Zone. (See Figure 5.) In the final analysis, little coverage of LAM SON 719 areas was possible due to "continuous close air support aircraft in 90 percent of the airspace. As the area shrank, it became impractical to work the INK system and its support of LAM SON 719 was curtailed on 20 Mar 71."

On 1 April 1971, "Speedy" TACP was inactivated and the 0-2A aircraft and four of the original pilots supporting the CORONET INK evaluation were transferred to the "Lopez" TACP where two other FACs joined them. In the new area of operation (AO), they were responsible for missions in the Quang Nam Sector of South Vietnam (see Figure 5) and in some of the special for interdiction areas of MR I. The area of operation included "an off-load point for enemy trucks, prior to moving supplies across the border [from Laos] into the Republic of Vietnam, and provided numerous targets

### TABLE 1

### CORONET INK SUPPORT

## OF LAM SON 719

Sorties		
Flown	Targets Sighted	Results
	21 Feb - 2 Mar 71	
3	22 10' x 20'	<pre>3 were struck yielding 3 destroyed trucks.</pre>
		10 were struck several times. Results unknown.
	1 10' x 20' (moving)	
	5 10' x 10' to 4' x 4'	
	3 Mar - 14 Mar 71	
6	6 10' x 20'	No air strikes were made on these targets due to
	3 personnel	higher priority targets (TIC, targets in the open)
	1 100mm gun	and weather.
	Numerous smaller targets	
	15 Mar - 23 Mar 71	
5	4 6' x 6' (suspected 37mm site)	No air strikes were made due to all fighters being
	4 10' diameter (in AA configuration)	used for close air support.

with minimum antiaircraft protection." Thus, it was an excellent area for 61 testing the INK equipment.

About the same time as the switch in TACPs, 7AF requested an extension of the CORONET INK program "to cover delays" in the evaluation of the program. On 7 April 1971, CSAF approved the request and extended the evaluation by 30 days to terminate 31 May 1971.

During this period, strike support was assured with fighters assigned 63 as a quick reaction force for Lopez INK sorties. Also, beginning 9 April 1971, the 7th AF fragged two INK sorties per day to STEEL TIGER with priority air available through Hillsboro Airborne Battlefield Command and Control Center (ABCCC) in addition to the ground alert F-4s. Results were immediately apparent as evidenced by this excerpt from 20th TASS's 5 April 64 through 11 April 1971 CORONET INK Status Report:

7. Strike Results: INK ground alert F-4s were scrambled five times against INK targets resulting in one truck destroyed, one raft destroyed, 3150 cu ft [of] supplies destroyed, two enemy personnel KBA [killed by air], seven secondary explosions, and ten sustained fires. Two other flights provided from Hillsboro ABCCC for INK targets resulted in one 37mm gun destroyed, one secondary explosion at gun position with black smoke to 500 feet, one elephant [towing supplies] KBA, and one sustained fire. . . .

10. During this period, eighty one INK targets were sighted and are now considered too numerous to report by size. All targets worth hitting were attacked.

Some interest had been expressed earlier by the Hq PACAF Director of Operations concerning a possible OV-10 PAVE NAIL (laser designator) 65 application for the INK equipment during the upcoming Commando Hunt VII. Therefore, while operating with the PAVEWAY F-4s, INK system operators attempted to detect the PAVEWAY laser beam. Although detection was not possible due to the short pulse width of the laser, they found that CORONET INK and PAVEWAY made an excellent team. INK found the target; 66 PAVEWAY destroyed it.

Seventh Air Force, feeling increased emphasis and more testing in Laos and Cambodia were necessary in order to complete the evaluation by the end of May 1971, encouraged 20th TASS to transfer the INK operation to the Covey TACP at Da Nang, whose mission was in Laos. The 20th TASS transferred the INK aircraft and the four original operators to Covey on 12 April 1971. They established an INK flight, added two more pilots, and began fragging the flight for two sorties per day in southern Laos, 57 staying clear of designated high threat areas as 7AF instructed. On 19 April 1971, however, INK operations expanded into VR sectors 12 and 13 of STEEL TIGER, roughly equivalent to new VR sectors six and seven (see Figure 5), to reach numerous lucrative targets. A day later 7AF removed the "high threat" restriction giving them complete freedom of movement in these sectors thereby significantly enhancing realistic combat evaluation. They also maintained close surveillance of the Ho 68 Chi Minh Trail along Routes 91 and 914.

Following the switch of the INK operation to Covey TACP, the INK operators had to familiarize themselves with the new area of operation.

Also, F-4 ground alert support had ceased on 17 April 1971 and renewal was not requested because support through Hillsboro was considered sufficient. However, during the following month, fighter support was often either non-existent or too late to be of any value. The result of the above combination of factors was a substantial reduction in the overall INK performance from mid-April to mid-May 1971.

Then, on 13 May 1971, INK operators began using the systems in support of a search and rescue (SAR) effort. The search was for a single individual whose only means of communication was a visual escape and evasion (E&E) code letter. Since the E&E letter was not necessarily an INK detectable target, the INK gear was not used exclusively. However, INK FACs, flying four sorties per day for a little over two weeks (a total of 66), assisted in the search of all suspect areas and sighted many enemy personnel although they were not attempting to locate enemy targets for destruction. This provided an excellent opportunity for evaluating the INK equipment in a SAR role, and the introduction team felt the system performed well in this capacity. The system had no capability for differentiating between enemy and friendly man-sized returns, however, and identification could be judged only on the basis of whether the man cooperated by remaining in view or signaling. Therefore, team members concluded that the system's identification capability could be significantly improved by incorporating stabilized binoculars. The SAR effort proved unsuccessful and terminated on 29 May 1971 as did the entire CORONA INK evaluation.

During the course of the CORONET INK evaluation in SEA, FACs using the INK systems detected 611 targets which were undetectable by other means. They varied in size from man-size to 20 meters by 60 meters. Most of the targets were three meters by three meters (probable supply stacks) or three meters by seven meters (probable vehicles). Fighters attacked 217 of the targets but had not attacked the remaining 394 because they were too small to be worthwhile, adverse weather prevented attack, or fighters were not available. However, the strikes had achieved the following results:

#### Target

37mm guns
Trucks
Trucks or vehicles
Supplies
Bunkers
Camouflaged road cover
Elephant (towing supplies)
\*Enemy personnel
Raft
Secondary explosions
Sustained fires

#### Results

five destroyed
11 destroyed
eight damaged
5,750 cubic feet destroyed
two destroyed
250 meters destroyed
one killed by air
13 killed by air
one destroyed
40
38

From a maintenance perspective, the five systems had operated 280 hours in the air (194 sorties) and 68 hours on the ground for a total of 348 hours during the three and one-half month evaluation. During this period, the equipment malfunctioned 45 times for a resultant 7.7 hours mean time between failures. Four of the systems were always in commission and all five were in commission 90 percent of the time with only about a 10 percent depletion of the 90-day parts kit. In addition, 20th TASS maintenance

<sup>\*</sup>Approximately 400 enemy personnel were detected with the INK equipment during CORONET INK evaluation. The largest group sighted consisted of 30 personnel; however, most were either single or in groups of two.

personnel in conjunction with introduction team members made the follow-72 ing modifications to the INK systems during the test:

- a. Designed, built, and installed new suspension hooks for all of the detector heads.
- b. Installed a mike button in the right handle on all detector heads.
- c. Replaced three-power solenoid switches with sealed switches as failures occurred.
- d. Added capacitors to detector printed circuit boards to obtain correct pulsing of trigger for square wave modulation of tubes in both phases.

As noted earlier in the report, tactics were modified upon arrival in SEA. The aircraft flew a right hand orbit and allowed the INK system to view the target at about a 45-degree angle. Thus the radius of the orbit was always approximately equal to the aircraft's height above the target. Where there was only a small arms or .50 caliber threat, the INK FAC maintained 3,200 feet altitude AGL. In areas where 23mm, 37mm, and 57mm guns were present, he flew at altitudes of 8,500 feet or higher.

73

No INK aircraft were damaged by ground fire during the test.

Training INK operators had been a major problem during the CORONET INK evaluation. At the conclusion of the test, two operators were qualified and four others were in various stages of training. The slow progress in this area was the result of several factors: (1) tactical mission requirements often took priority; (2) each time the INK flight was switched to a new TACP, some INK instruction time was lost while the pilots became familiar with the new AO; (3) since the training was conducted in actual combat areas, controlled targets could not be used; (4) the enemy used

mostly natural camouflage (foliage) and most targets detected resulted from enemy movements or poor camouflage; and (5) since the INK equipment provided no method for identifying the type of target detected or of easily eliminating natural targets, operators had to resort to the cumbersome procedure of using auxiliary binoculars which proved extremely difficult 74 for trainees.

When the introduction team chief debriefed the operators at the termination of the test, "Operators with over 25 hours on the INK system felt that they could find targets. All operators felt that the INK system was difficult to use. All qualified operators wanted to keep the INK system with 75 the 20th TASS after the evaluation was complete."

At the conclusion of the test, the introduction team chief and USAFTAWC recommended that the five INK systems remain with the 20th TASS, and 7AF concurred. However, 7AF stated that they had no requirement for any additional INK system procurement in view of the SEA phasedown and the adequacy of system quantities already in SEA. The INK program remained in operational use by the 20th TASS for another year.

Coincident with the termination of the CORONET INK test phase on 29 May 1971, the INK flight began operating throughout VR sectors four through nine in STEEL TIGER. (See Figure 5.) Except for an occasional mission in MR I in RVN, they operated mostly in the STEEL TIGER area for the remainder of their time in SEA.

INK missions into STEEL TIGER out of Da Nang AB taxed the weight and endurance capability of the 0-2A. With the added weight of the second

pilot (INK operator), the INK equipment, and sufficient fuel for the mission, the aircraft routinely took off from Da Nang AB with the maximum weight possible. Enroute time to and from the AO averaged about one hour in each direction. This coupled with an average two and one-half to three hours station time totaled about four and one-half to five hours per mission or near maximum endurance under those operational conditions. In fact, some station times had to be reduced by 15 to 25 minutes because of the additional weight. In short, the O-2A was not designed to carry the weight 78 which the INK missions over STEEL TIGER demanded of it.

Another problem imposed on the 0-2A by operations in some parts of STEEL TIGER was that of altitude limitations. The terrain was high, often rising to 5,000 feet or more. Since the 0-2A carried no supplemental oxygen, the crews could not exceed 10,000 feet. This placed them well within range of any of the larger guns in the area although they were only occasionally fired upon and none were ever hit. The guns, however, did force 79 them to fly well above INK's most effective altitude of 3,200 feet AGL.

During actual combat employment, the INK equipment performed best when used in a supplementary role and when teamed with the 20 power stabilized binoculars. On a standard mission, the INK operator would check with the ABCCC when arriving on station, ascertain if any of the controlling FACs in the area had any targets which they wanted "INKed," and if not would either proceed to check out targets provided by intelligence or search for targets of opportunity. When looking for targets of opportunity, the normal practice was to take the detector head out of the

window and go straight VR using the hand held, 10 power binoculars. If the operator located a likely target, he would put the detector head back in the window and, using the three power lens to orient himself, would check it out with the INK system. If INK returns appeared, he would then use the 20 power stabilized binoculars for a closer view to eliminate natural targets. After verifying the target and determining whether it appeared lucrative enough to merit a strike, he would locate it for the controlling FAC in the area who would then direct the strike. Or, if the other FAC was busy, he could put the strike in himself. Some of the INK operators felt that having to "hand off" their targets to another FAC was cumbersome and that it would have been much better for them to put in all of the strikes against 80 their own targets whenever possible.

During November 1971, INK FACs began flying in support of Project Island Tree which was an effort by Task Force Alpha (TFA) to target large concentrations of NVA troops in supply areas and rest stops along the Ho Chi Minh Trail in STEEL TIGER. Once TFA established the acoustically targeted areas (ATAs) using multi-source intelligence (including INK VR), ARC LIGHT missions were scheduled against them while TFA used pre-dropped acoustical sensors to aid in bomb damage assessment. The project, including INK support, continued throughout the dry season in STEEL TIGER, ending 81 about March 1972.

On 23 November 1971, Aerospace Systems Division advised 7AF and 20th TASS that ASD was investigating an improved target marking capability for designating camouflaged targets found by the INK device. The item under

consideration was a light weight laser illuminator developed by International Laser System. It had dimensions of four and one-half by five by 14 inches, weighed about eight pounds, and was compatible with laser seekers aboard fighter aircraft. As envisioned, it would have either been hand held or mounted on the INK device with the beam folded through the optics and out through the stabilized dynalens subsystem. However, on 10 December 1971, ASD shelved the idea indefinitely when it appeared several of the operational INK units would be required for installation in Credible Chase aircraft, leaving none available for 82 testing.

During December 1971, the Air Staff considered including one or more of the INK systems in the CREDIBLE CHASE combat evaluation. However, shortly thereafter, they terminated the proposed inclusion of 83 INK without providing rationale.

As noted earlier in this report, maintenance personnel supported a 90 percent in-commission rate for the five INK systems during CORONET 84
INK with only about a 10 percent depletion of the spare parts. Then on 1 October 1971, 20th TASS advised 7AF that the dynalenses in all five detector heads were leaking oil. While they could be refilled, realignment was required with each oil service, necessitating six hours maintenance time per set. They also reported that both spare dynalenses were clouded on the inside and therefore unusable. The dynalens was a vital part of the system and could only be repaired or replaced on an individual 85

About the same time, the spare parts kit was beginning to dwindle. This in conjunction with the dynalens problem marked the beginning of a continuing struggle for maintenance, parts, and funds which continued through the end of INK's SEA employment.

By the Spring of 1972, although the INK systems were often used for up to four missions per day giving sunrise to sunset VR coverage, they were breaking down more often and becoming increasingly difficult to maintain. Two of the five systems were almost constantly in a not operationally ready, due to lack of supplies (NORS) condition. Supply was a major problem as parts had to be individually ordered and produced and, therefore, were expensive. Also, since the parts were produced on an "as needed" basis, considerable time elapsed before the replacement parts were received by 20th TASS. Thus 20th TASS maintenance personnel were frequently forced to resort to cannibalization in order to keep at least three of the systems 87 operational.

On 31 March 1972, PACAF provided funds to cover spare parts procurement through the end of the dry season and advised 7AF that the INK operation faced three alternatives:

- Terminate INK operations upon depletion of the spares inventory.
- Establish a requirement for additional production systems to include entry into the USAF logistics system.
- c. Continue operations and support of the five existing devices for an additional year.

SECRET

PACAF asked that 7AF evaluate their future requirement for INK systems and 88 comment on the desired alternative. Seventh Air Force responded by saying that the INK program in SEA would be terminated not later than 30 June 89 1972 and requested shipping instructions for the INK equipment. Actual INK operations in SEA ceased about 7 April 1972 with the start of the North Vietnamese (NVN) Spring Offensive, and the aircraft and crews which had been used in support of the INK program were assigned to fly regular FAC missions.

Although apparently no one item sounded the death knell for INK's operational employment, several factors seem to have contributed to its early demise. They were as follows:

- a. Since the INK devices were prototype units and were never entered into the Air Force logistics system, replacement parts had to be requisitioned and produced on an "as required" basis. Therefore, parts and stateside maintenance were quite expensive and often very slow in responding to operational requirements.
- b. The problem with supplies and spare parts was compounded by the fact that the company which engineered and manufactured the major subassemblies of the system went out of business shortly after they delivered the last INK system to USAFSOF.
- c. There was no "pool" of trained personnel. All personnel had been trained in the field by the introduction team, and no provision was made for continental United States (CONUS) training of operators or maintenance 91 personnel.

- d. Seventh Air Force had determined that there was no USAF requirement for any more of the systems in SEA nor was there any Vietnamese Air 92

  Force (VNAF) requirement for them.
- e. Twentieth TASS urgently needed the aircraft and crews which had supported the INK operation for normal FAC missions in countering the NVN Spring Offensive.
- f. With the start of the Spring Offensive, targets were so plentiful that the INK equipment was not really necessary. The problem was no longer one of finding targets but rather one of destroying them.

On 30 May 1972, ASD asked 7AF to ship all of the INK equipment to them when its operational employment was terminated. The 366 TFW (host base) at Da Nang AB forwarded the equipment to ASD at Wright Patterson AFB, Ohio, on 24 June 1972 officially and finally terminating its presence in Southeast 94 Asia.

#### CHAPTER IV

#### SUMMARY

with the benefit of a retrospective view of the entire INK program including HAVE INK, HAVE INK II, COMBAT INK, CORONET INK, and the follow-on combat employment, individuals and units involved with the program drew certain conclusions and made certain recommendations.

The 0-2A modification was acceptable as configured and required no maintenance. With the required kits available, modifications can be accomplished in the field in less than two hours per aircraft.

If necessary, maintenance training can be conducted in the field; however, large groups could be more effectively trained in the CONUS by Air Training Command. Air Force maintenance personnel can fully maintain the INK system if they have the required parts available.

Whenever possible, operator training should not be conducted in a combat zone. Lack of controlled targets in jungle terrain severely limited and slowed operator training. Also, all operators were pilots; this created a morale problem for young pilots who wanted to devote 100 percent of their flying time to pilot duties.

Combat tactics as employed in SEA were successful. The INK crews were exposed to no unnecessary risks, and the results they obtained were good.

Combat results definitely indicate that the INK device was a valuable asset to the FAC and was most effectively used as a complement to other FAC equipment in detecting enemy targets.

The INK system had two main deficiencies which require correction:

First, the unstabilized three-power locating subsystem was difficult to use in pinpointing targets previously detected. It was too weak and too unstable. Second, the system included no means for identifying targets. It was impossible in most cases to determine what the targets were until after they had been attacked and exposed from their camouflaged positions. Thus FACs had to use hand-held binoculars above 3,000 feet AGL in order to eliminate natural targets. A modification to include an identification feature could vastly improve the equipment's operational effectiveness and capability.

Many targets detected by use of the INK system could not be visually acquired by strike aircraft called in by the FACs. Therefore, a laser designator or other similar device could provide an acceptable marking 95 system for directing attacking aircraft.

The INK system appeared to have distinct possibilities for use in a SAR role, either military or civilian. This would be especially true if "cooperating materials" could be perfected and used to identify the object 96 of the search.

Recommendations for solving some of the problems raised during the INK operational employment may be found in the Appendix.

Thus the INK system was conceived, developed, employed in a combat environment, and finally shelved indefinitely. Only time, future requirements perhaps in other theaters, available funds, competing technology, and other such considerations will determine whether it is ever reintroduced.

#### APPENDIX

#### FIELD RECOMMENDATIONS ON INK PROGRAM

The three power locating subsystem should be deleted and a tube and filter bypass added to provide direct viewing through the stabilizer. Also the seven and fifteen power lenses should be replaced with a seven to fifteen or seven to twenty powered zoom lens to assist the operator in locating targets. In operation, this would allow a change of scene to real life for identification after an INK target is sighted and then a zoom back to lower power to locate it.

Other recommended modifications to the detector head were as follows.

First, since there were too many controls on the right side of the head to be operated with the right hand, the mike button should be moved to the left side. Second, the case material became soft and deformed when exposed to sunlight and heat for prolonged periods on the ground and should be replaced. Third, an effort should be made to reduce the weight of the head to the point where it could be hand-held thereby allowing increased mobility and less vibration. Fourth, the automatic iris feature should be replaced with a manual control. Fifth, since the binocular eyepiece required expensive and critical assembly and alignment, it should be redesigned. Sixth, the objective lens should be focusable so that image-tube replacement is less critical. The photo cathode position was critical to within 0.010 inch because of the fixed-focus objective design.

If the system is ever rejuvenated and future requirements established, consideration should be given to adapting the equipment to a turret mount

with a co-aligned laser marking system. One possibility would be to 99 incorporate it in the PAVE NAIL pod on the OV-10.

Operators should be trained before operating in a combat environment.

They should also be persons (either officers or enlisted) who are dedicated to operating the INK equipment as opposed to pilots who had to perform their loo primary flying duties at least 50 percent of the time.

In order to give the INK system a larger operating area and to overcome the deficiencies of the 0-2A mentioned earlier, the equipment should
be installed in a more powerful aircraft. Although the OV-10 was previously
ruled out because of interference with the ejection seat, it or a similar
aircraft should be considered for future INK operations.

A THE STATE OF THE PROPERTY OF

#### **FOOTNOTES**

- 1. Msg (S), DCS/Plans, Hq 7AF to CINCPACAF, 220200Z Aug 71.
- 2. Talking paper (S), 20 TASS, Subj: 20 TASS FAC Operations in MR I, 17 Jul 71, Project CHECO microfilm roll (CMR) Secret #525, 004.
- 3. Briefing (C), USAFSOF, Subj: CORONET INK Ingress, 8 Feb 71 [hereinafter cited as CORONET INK Ingress Briefing]; Technical Report No. AFWL-TR-70-62 (C), Advanced Direct-Viewing Camouflage Detector (COMBAT INK), Oct 1970 [hereinafter cited as AFWL-TR-70-62], p. ii.
- 4. CORONET INK Ingress Briefing (C); TAC OPLAN 19, Subj: CORONET INK Deployment and Evaluation Plan (C), 8 Sep 70, p. 1 [hereinafter cited as TAC OPLAN 19]; Final Report (S), CORONET INK (COMBAT INK Combat Evaluation), USAFTAWC, Sep 1971 [hereinafter cited as CORONET INK Final Report], p. 1.
- 5. AFWL-TR-70-62 (C), p. 3; CORONET INK Final Report (S), p. 1.
- 6. AFWL-TR-70-62 (C), p. 14.
- 7. Ibid.
- 8. CORONET INK Final Report (S), p. 1.
- 9. AFWL-TR-70-62 (C), p. 10.
- 10. CORONET INK Final Report (S), p. 1.
- 11. AFWL-TR-70-62 (C), p. 3.
- 12. CORONET INK Final Report (S), p. 1.
- 13. <u>Ibid</u>.
- 14. Final Report (C), COMBAT INK, USAFTAWC, Aug 1971 [hereinafter cited as COMBAT INK Final Report], p. 1; AFWL-TR-70-62 (C), p. 5.
- 15. AFWL-TR-70-62 (C), p. 1.
- 16. COMBAT INK Final Report (C), p. 1.
- 17. CORONET INK Final Report (S), p. 2.

- 18. AFWL-TR-70-62 (C), p. 5; CORONET INK Ingress Briefing (C); COMBAT INK Final Report (C), p. 1.
- 19. AFWL-TR-70-62 (C), p. 5.
- 20. Ibid., pp. iii, 5.
- 21. Ibid., p. 41.
- 22. Ibid.; COMBAT INK Final Report (C), p. 2.
- 23. COMBAT INK Final Report (C), p. 2.
- 24. <u>Ibid.</u>, p. 31; Ltr (C), USAFSOF to CINCPACAF, Subj: Slides of INK System and Typical Targets, 23 Sep 70.
- 25. COMBAT INK Final Report (C), pp. 5, 19.
- 26. Ibid., p. 4; Ltr (C), USAFSOF to CINCPACAF, Subj: Slides of INK System and Typical Targets, 23 Sep 70.
- 27. COMBAT INK Final Report (C), pp. 4, 5; CORONET INK Final Report (S), p. 17; Armament Development and Test Center, "COMBAT INK," a special film (C) produced to document portions of the results of TAC Test 69-226 (SOF Test 2V-64) [hereinafter cited as COMBAT INK Film].
- 28. COMBAT INK Final Report (C), p. 5; CORONET INK Final Report (S), p. 17; Msg (S), 20 TASS to 7AF, 260730Z Aug 71, CMR S-525, 050; Msg (S), 20 TASS to 7AF, 031210Z Sep 71, CMR S-525, 042; Msg (S), 20 TASS to 7AF, 170515Z Sep 71, CMR S-525, 042; COMBAT INK Film (C).
- 29. COMBAT INK Final Report (C), pp. 5, 6. CORONET INK Ingress Briefing (C), p. 2.
- 30. CORONET INK Ingress Briefing (C), p. 4.
- 31. Msg (C), DCS/Rqmts, Hq TAC to CSAF, 221336Z Jan 71; TAC OPLAN 19 (C), pp. 0-1.
- 32. COMBAT INK Final Report (C), p. 7.
- 33. AFWL-TR-70-62 (C), p. 41.
- 34. CORONET INK Ingress Briefing (C), p. 2.; Msg (C) DCS/Rqmts, Hq TAC to CSAF, 221336Z Jan 71; Msg (C) DCS/Rqmts, Hq TAC to CINCPACAF, 301600Z Jun 70.

- 35. COMBAT INK Final Report (C), pp. 7, V; Msg (C), DCS/Rqmts, Hq TAC to CINCPACAF, 131935Z Aug 70.
- 36. COMBAT INK Final Report (C), p. 39; Msg (C), DCS/Rqmts, Hq TAC to CSAF, 221336Z Jan 71.
- 37. COMBAT INK Final Report (C), p. 7; CORONET INK Final Report (S), p. 2.
- 38. COMBAT INK Final Report (C), p. 9; COMBAT INK Film (C).
- 39. Ibid.
- 40. Ibid., p. 8.
- 41. CORONET INK Final Report (S), p. iii.
- 42. CORONET INK Ingress Briefing (C), p. 6.
- 43. Msg (C), 20 TASS to USAFSOF, 110540Z Feb 71; CORONET INK Ingress Briefing (C), pp. 5, 6.
- 44. CORONET INK Final Report (S), p. 2.
- 45. Ibid.; Msg (S), I DASC to CSAF, 151021Z Feb 71.
- 46. CORONET INK Final Report (S), pp. 3, 25.
- 47. Intvw (S), author with Capt Ronald R. Jones, 20 TASS, 16 Jan 73 [hereinafter cited as Jones Intvw]; Ltr (S), 20 TASS to 504 TASG, Subj: 20th TASS Primary Mission Requirements and Capabilities, 2 Sep 71, CMR S-525, 006.
- 48. CORONET INK Ingress Briefing (C), p. 6; TAC OPLAN 19 (C), p. 4.
- 49. Msg (C), DCS/Plans, 7AF to CINCPACAF, 220201Z Jun 70.
- 50. CORONET INK Final Report (S), p. 31.
- 51. Ibid., pp. 3, 4, 45.
- 52. Ibid., pp. 3, 4, 43; TAC OPLAN 19 (C), p. 1.
- 53. Msg (S), I DASC to CSAF, 230210Z Feb 71.
- 54. COMBAT INK Final Report (C), p. 5; Jones Intvw (S).

- 55. Project CHECO Southeast Asia Report (S), Lam Son 719 30 Jan-24 Mar 1971 the South Vietnamese Incursion into Laos, 24 Mar 71, p. 1.
- 56. Msg (S), DCS/Ops, 7AF to 504 TASG, I DASC, 031200Z Mar 71.
- 57. Msg (S), I DASC to CSAF, 100300Z Mar 71; Msg (S), I DASC to CSAF, 161030Z Mar 71; Msg (S), I DASC to CSAF, 290225Z Mar 71.
- 58. CORONET INK Final Report (S), p. 31.
- 59. Msg (S), I DASC to CSAF, 290225Z Mar 71.
- 60. Staff Summary Sheet (S), 7AF, Dir/Comd and Con to DCS/Ops, Subj: CORONET INK System, 27 Mar 71, CMR S-557, 218; Msg (S), I DASC to CSAF, 290225Z Mar 71.
- 61. CORONET INK Final Report (S), p. 4.
- 62. Msg (S), I DASC to CSAF, 290225Z Mar 71; Msg (U), C/S, 7AF to COMUSMACV, 010401Z Apr 71; Msg (C), DCS/Plans, CSAF to TAC, 071559Z Apr 71; Memo (S), DCS/Ops to CINCPACAF, Subj: CORONET INK Evaluation, 31 Apr 71; Fact Sheet (S), Hq PACAF, Subj: CORONET INK, 1 May 1971.
- 63. Msg (S), I DASC to CSAF, 060716Z Apr 71.
- 64. Msg (S), 20 TASS to CSAF, 120850Z Apr 71.
- 65. Msg (S), DCS/Ops, PACAF to 7AF, 020222Z Apr 71.
- 66. Msg (S), 20 TASS to CSAF, 120850Z Apr 71.
- 67. Msg (S), DCS/Ops, 7AF to 504 TASG, 20 TASS, 100315Z Apr 71; Msg (S), I DASC to CSAF, 290225Z Mar 71; Msg (S), 20 TASS to CSAF, 120850Z Apr 71; CORONET INK Final Report (S), p. 4; Msg (S), 20 TASS to 7AF, 150500Z Apr 71, CMR S-525, 035.
- 68. Msg (S), 20 TASS to CSAF, 190245Z Apr 71; Msg (S), DCS/Ops, 7AF to 504 TASG, 20 TASS, 200204Z Apr 71, CMR S-557, 216; CORONET INK Final Report (S), p. 31.
- 69. Msg (S), 20 TASS to CSAF, 190245Z Apr 71; Msg (S), 20 TASS to CSAF, 252353Z Apr 71; Msg (S), 20 TASS to CSAF, 030850Z May 71; Msg (S), 20 TASS to CSAF, 100755Z May 71; Msg (S), 20 TASS to CSAF, 180145Z May 71.
- 70. Msg (S), 20 TASS to CSAF, 180145Z May 71; Msg (S), 20 TASS to CSAF, 240155Z May 71; Msg (S), 20 TASS to CSAF, 010813Z Jun 71; CORONET INK Final Report (S), p. 6; Briefing (S), USAFTAWC, Subj: CORONET INK Briefing, 3 Jun 71, p. 6 [hereinafter cited as CORONET INK Egress Briefing].

- 71. CORONET INK Final Report (S), pp. 5, 6, 48.
- 72. Ibid., pp. 39, 4; Ltr (C), USAFTAWC to TAC, Subj: CORONET INK Parts Support, 19 Oct 71.
- 73. CORONET INK Final Report (S), p. 5.
- 74. Ibid., pp. 4, 5; CORONET INK Egress Briefing (S), p. 2.
- 75. CORONET INK Final Report (S), p. 5.
- 76. Ltr (C), USAFTAWC to TAC, Subj: CORONET INK Parts Support, 19 Oct 71; CORONET INK Final Report (S), p. 16; Msg (S), DCS/Plans, 7AF to CINCPACAF, 230201Z Aug 71.
- 77. Staff Summary Sheet (S), 7AF, Dir/Comd and Con to Comdr, Subj: CORONET INK/Island Tree Operation, 11 Nov 71, CMR S-557, 220.
- 78. Jones Intvw (S); Msg (S), 20 TASS to 504 TASG, Sep 71, CMR S-525, 002.
- 79. Jones Intvw (S); COMBAT INK Final Report (C), p. 7.
- 80. Jones Intvw (S); Intvw (S), author with 1Lt Joseph M. Jewel, 71 ARS (formerly assigned to 20 TASS), 5 Apr 73 [hereinafter cited as Jewel Intvw].
- 81. Staff Summary Sheet (S), 7AF, Dir/Comd and Con to DCS/Ops, Subj: CORONET INK/Island Tree Operation, 11 Nov 71, CMR S-557, 220; Intvw (S), author with 1Lt Curtis E. Perkins, 346 Bombardment Sqn (formerly assigned to 20 TASS), 28 Mar 73 [hereinafter cited as Perkins Intvw]; Intvw (S), author with Capt Robert K. Tiernan, 13th ADVON/Intel (formerly assigned to TFA), 7 Jun 73.
- 82. Msg (C), ASD to TAC et al, 231923Z Nov 71; Msg (C), ASD, to 7AF, 102120Z Dec 71.
- 83. Msg (S), Dir/Rqmts, PACAF to 7AF, 300201Z Nov 71; Msg (S), DCS/Plans, CSAF to CINCPACAF, 092023Z Dec 71; Memo (S), Dir/Rqmts to DCS/Ops, PACAF, Subj: COMBAT INK Camouflage Detectors, 16 Mar 72.
- 84. CORONET INK Final Report (S), p. 4; Ltr (C), USAFTAWC to TAC, Subj: CORONET INK Parts Support, 19 Oct 71.
- 85. Msg (S), 20 TASS to 7AF, 010750Z Oct 71, CMR S-525, 044; Ltr (C), USAFTAWC to TAC, Subj: CORONET INK Parts Support, 19 Oct 71.

- 86. Ltr (C), USAFTAWC to TAC, Subj: CORONET INK Parts Support, 19 Oct 71; Msg (C), DCS/Log, 7AF to 20 TASS, 040946Z Nov 71; Msg (C), ASD to TAC, 231923Z Nov 71; Msg (S), DCS/Log, 7AF to ASD, 300200Z Dec 71; Msg (C), Dir/Rqmts, PACAF to AFSC, 082321Z Mar 72; Msg (S), DCS/Ops, PACAF to CSAF, 160502Z Mar 72; Msg (C), Dir/Rqmts, PACAF to ASD, 310144Z Mar 72; Jones Intvw (S); Perkins Intvw (S).
- 87. Jones Intvw (S); Perkins Intvw (S).
- 88. Msg (C), Dir/Romts, PACAF to ASD, 310144Z Mar 72.
- 89. Msg (C), DCS/Ops, 7AF to PACAF, 280115Z Apr 72.
- 90. Perkins Intvw (S); Jones Intvw (S).
- 91. Memo (S), Dir/Rqmts to DCS/Ops, PACAF, Subj: COMBAT INK Camouflage Detectors, 16 Mar 72; Memo (S), Dir/Rqmts to DCS/Ops, PACAF, Subj: COMBAT INK for Search and Rescue, 6 Jun 72; Msg (S), DCS/Ops, PACAF to CINCPAC, 100337Z Jun 72.
- 92. Msg (S), DCS/Plans, 7AF to CINCPACAF, 230201Z Aug 71; Msg (S), DCS/Ops, 7AF to CINCPACAF, 110600Z Mar 72; Msg (S), DCS/Ops, PACAF to CSAF, 160502Z Mar 72.
- 93. Perkins Intvw (S); Jones Intvw (S); Jewel Intvw (S).
- 94. Msg (U), ASD to 7AF, 301845Z May 72; Msg (U), 366 TFW to ASD, 270415Z Jun 72.
- 95. CORONET INK Final Report (S), pp. 3, 16; CORONET INK Egress Briefing (S), pp. 9, 10; Jewel Intvw (S); Jones Intvw (S).
- 96. Perkins Intvw (S); AFWL-TR-70-62 (C), p. 46.
- 97. CORONET INK Final Report (S), p. 16; Jones Intvw (S); CORONET INK Egress Briefing (S), p. 11.
- 98. CORONET INK Egress Briefing (S), p. 7; Jones Intvw (S); AFWL-TR-70-62 (C), p. 45.
- 99. CORONET INK Final Report (S), p. 16.
- 100. CORONET INK Egress Briefing (S), p. 11; Perkins Intvw (S).
- 101. Jones Intvw (S).

#### **GLOSSARY**

Antiaircraft AA Antiaircraft Artillery AAA Air Base AB Airborne Battlefield Command and Control Center **ABCCC** Air Force AF Air Force Base AFB AFSC Air Force Systems Command Air Force Weapons Laboratory AFWL Above Ground Level AGL Area of Operation A0 Aerospace Systems Division ASD Acoustically Targeted Area ATA Bomb Damage Assessment BDA CD Camouflage Detection CHECO Microfilm Roll CMR Continental United States CONUS (S) A light, short takeoff and landing transport/mini-CREDIBLE CHASE gunship concept. CSAF Chief of Staff, Air Force Direct Air Support Center DASC Direct Current DC E&E Escape and Evasion Forward Air Controller FAC

GP General Purpose

IR Infrared

KBA Killed by Air

mm Millimeter Military Region

NORS Not Operationally Ready, Supply
NVA North Vietnamese Army

NVN North Vietnamese

OJT On-the-Job Training
OT&E Operational Test and Evaluation

QRF Quick Reaction Force

RADC Rome Air Development Center

RVN Republic of Vietnam

SAR Search and Rescue SEA Southeast Asia

TAC Tactical Air Command

TACP Tactical Air Control Party
TASS Tactical Air Support Squadron

TFA Task Force Alpha
TFW Tactical Fighter Wing
TIC Troops in Contact

U.S. United States

USAF United States Air Force

USAFSOF United States Air Force Special Operations Force
USAFTAWC United States Air Force Tactical Air Warfare Center

VC Viet Cong

VNAF Vietnamese Air Force VR Visual Reconnaissance